

dzufelt@greenanalytical.com p: 970.247.4220 f: 970.247.4227 75 Suttle Street Durango, CO 81303

www.GreenAnalytical.com

Hilcorp

3401 30th Street

Farmington NM, 87401

Project: Braden Head

Project Name / Number: Asset: South

Project Manager: David Bounds

Reported:

09/13/18 12:45

Starr 1 API # 30-045-06 Dele

1809031-02 (Water)

Result	RL	MDL	Units	Dilution	Analyzed	Method	Notes	Analyst
17.8	25.0	4.82	mg/L	25	09/06/18	EPA300.0		AES
10.8			pH Units	1	09/07/18	EPA150.1	HI	JDU
700	10.0		mg/L	1	09/07/18	EPA160.1	Hl	1DU
178	25.0	7.38	mg/L	25	09/06/18	EPA300.0		AES
	17.8 10.8 700	17.8 25.0 10.8 700 10.0	17.8 25.0 4.82 10.8 700 10.0	17.8 25.0 4.82 mg/L 10.8 pH Units 700 10.0 mg/L	17.8 25.0 4.82 mg/L 25 10.8 pH Units 1 700 10.0 mg/L 1	17.8 25.0 4.82 mg/L 25 09/06/18 10.8 pH Units 1 09/07/18 700 10.0 mg/L 1 09/07/18	17.8 25.0 4.82 mg/L 25 09/06/18 EPA300.0 10.8 pH Units 1 09/07/18 EPA150.1 700 10.0 mg/L 1 09/07/18 EPA160.1	17.8 25.0 4.82 mg/L 25 09/06/18 EPA300.0 10.8 pH Units 1 09/07/18 EPA150.1 H1 700 10.0 mg/L 1 09/07/18 EPA160.1 H1

Green Analytical Laboratories

Dellie Zufett

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety. In no event shall Green Analytical Laboratories be liable for incidental or consequential damages. GALs liability, and clients exclusive remedy for any claim arising, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever, shall be deemed waived unless made in writing and received within thirty days after completion of the applicable service.