

Sulfate\*

## dzufelt@greenanalytical.com p: 970.247.4220 f: 970.247.4227 75 Suttle Street Durango, CO 81303

Laboratories			***				www.Gre	enAnalytical	.com	
Hilcorp		I	Project: Brad	ien Head						
3401 30th Street	Project Name / Number: Asset: South							Reported:		
Farmington NM, 87401	Project Manager: David Bounds							09/13/18 12:45		
			ewsom B Area 6 9031-03 (W		T#	30-04	15-341	77		
Analyte	Result	RL	MDL	Units	Dilution	Analyzed	Method	Notes	Analyst	
General Chemistry										
Chloride*	67.0	25.0	4.82	mg/L	25	09/07/18	EPA300.0		AES	
pH*	12.3			pH Units	1	09/07/18	EPA150.1	Hl	JDU	
Total Dissolved Solids*	1780	20.0		mg/L	2	09/07/18	EPA160.1	HI	JDU	

7.38

mg/L

25

09/07/18

255

25.0

Green Analytical Laboratories

in Zufett

Debbie Zufelt, Reports Manager

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety. In no event shall Green Analytical Laboratories be liable for incidental or consequential damages. GALs liability, and clients exclusive remedy for any claim arising, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever, shall be deemed waived unless made in writing and received within thirty days after completion of the applicable service.

EPA300.0

AES