

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director
Oil Conservation Division



September 20, 2018

DJR Operating, LLC
Attn: Amy Archuleta
1 Road 3263
Aztec, NM 87410

Re: 2018 Bradenhead Test
Well: A P Hixon Com #1E, UL A Sec 21 Twn 25N Rge 11W, API # 30-045-26036

Dear Ms. Archuleta:

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **October 20, 2018**, and initiate remedial activity before **December 20, 2018**. The initial Surface Casing psi was 26. The initial Production Casing psi was 25. Bradenhead equalizes with production casing.

Gas analysis has been received. Gas appears to be the same on the bradenhead and the production casing. Please submit wellbore schematic that includes formation and cement tops

Reference: RBDMS MPK1826357366 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File