

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director
Oil Conservation Division



September 21, 2018

Huntington Energy, LLC
Attn: Catherine Smith
908 NW 71st
Oklahoma City, OK 73116-3116

Re: 2018 Bradenhead Test
Well: Ute Mountain Ute #80, UL B Sec 20 Twn 32N Rge 14W, API # 30-045-34513

Dear Ms. Smith:

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **October 21, 2018**, and initiate remedial activity before **December 21, 2018**. The initial Surface Casing psi was 34. The initial Production Casing psi was 0. Pressures taken at 5, 10, and 15 minute intervals show a constant 34 psi on bradenhead. The five minute Surface Casing shut in pressure was 34.

Gas analysis has been received. Gas appears to be the same on bradenhead and production casing. Please submit wellbore schematic that includes formation and cement tops.

Reference: RBDMS MPK1804625814 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File