

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NMOC
Form C-141
Revised April 3, 2017
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
DISTRICT III

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Hilcorp Energy Company	Contact Clara Cardoza
Address 382 CR 310 Aztec NM 87410	Telephone No. 505-564-0733
Facility Name P O Pipkin 2F	Facility Type Well

Surface Owner Federal	Mineral Owner Federal	API No. 30-045-32676
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 08	Township 27N	Range 10W	Feet from the 660	North/South Line North	Feet from the 1965	East/West Line West	County San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude 36.584328 Longitude -107.920587 NAD83

NATURE OF RELEASE

Type of Release Compressor oil/produced oil	Volume of Release 24 bbl	Volume Recovered 24 bbl
Source of Release Pit Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 06/19/2018 14:53
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Underestimated production of fluids and delayed visit to facility resulted in well tank over the top. Vac truck was called to pull contents of tank and pit.

Describe Area Affected and Cleanup Action Taken.*

Tank was pulled and lined pit was cleaned with a soapy water wash. Pit liner appeared to be in excellent condition. All fluids were removed with a vac truck; tank was reset and placed back in service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Clara Cardoza	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: <u>7/23/18</u>	Expiration Date:
E-mail Address: ccardoza@hilcorp.com	Conditions of Approval: <u>—</u>	Attached <input type="checkbox"/>
Date: 07/03/2018	Phone: 505-564-0733	

* Attach Additional Sheets If Necessary

NVE 1820429779