

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company LOGOS Operating, LLC	Contact Larissa Farrell
Address 2010 Afton Place Farmington, NM 87401	Telephone No. (505) 787-2027
Facility Name Chaco 2308 03 1H & 2H	Facility Type

Surface Owner Federal	Mineral Owner Federal	API No. 30-045-35647
-----------------------	-----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter H	Section 03	Township 23N	Range 08W	Feet from the 2013	North/South Line North	Feet from the 186	East/West Line East	County San Juan County
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------------------

Latitude 36.258023 Longitude -107.660784 NAD83

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release Approx 15 BBLS	Volume Recovered 0
Source of Release pin hole leak in heater treater line	Date and Hour of Occurrence unknown	Date and Hour of Discovery 8/11/2018 10:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

**NMOCD**  
**AUG 22 2018**  
**DISTRICT III**

Describe Cause of Problem and Remedial Action Taken.\*  
Heater treater underground line had a pin hole leak. Operator identified the release and immediately shut in well. The contaminated soil was hydrovac and hauled out.

Describe Area Affected and Cleanup Action Taken.\*  
Release occurred under the liner in the secondary containment. Continuing to dig, haul and remediate. Will provide confirmation sample once remediation efforts are complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Larissa Farrell	Approved by Environmental Specialist: 	
Title: Environmental/Regulatory Technician	Approval Date: 9/10/2018	Expiration Date:
E-mail Address: lfarrell@logosresourcesllc.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/21/2018	Phone: (505)419-1100	

\* Attach Additional Sheets If Necessary

NVF 1824055063