



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-21-2018 Operator Western Minerals & Oil API # 30-045-06414

Property Name Marron Well No. 3 Location: Unit D Section 24 Township 27N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 13 Intermediate -- Casing 15 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>	<u>---</u>	<u>15</u>		
10 min	<u>0</u>	<u>---</u>	<u>15</u>		
15 min	<u>0</u>	<u>---</u>	<u>15</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE --

REMARKS:

Blew down in 1 second

By Bob Chenault

Witness Tarence Arellano

Pumper
(Position)

E-mail address bob@ccinm.com

NMOCD
SEP 27 2018
DISTRICT III