

dzufelt@greenanalytical.com p: 970.247.4220 f: 970.247.4227 75 Suttle Street Durango, CO 81303

Laboratories	· · · · ·						www.Gr	eenAnalytical	.com	
Hilcorp		I	Project: Brac	len Head						
3401 30th Street	Project Name / Number: Asset: South							Reporte	Reported:	
Farmington NM, 87401	Project Manager: David Bounds							09/13/18 1	2:45	
		Ge-		ithe 2 AT	PI #	30-00	45-118	34		
			Area 6							
		180	9031-08 (W	/ater)						
Analyte	Result	RL	MDL	Units	Dilution	Analyzed	Method	Notes	Analyst	
General Chemistry										
Chloride*	15.9	25.0	4.82	mg/L	25	09/07/18	EPA300.0		AES	
H*	11.0			pH Units	1	09/07/18	EPA150.1	HI	JDU	
fotal Dissolved Solids*	725	10.0		mg/L	1	09/07/18	EPA160.1	HI	JDU	
Sulfate*	101	25.0	7.38	mg/L	25	09/07/18	EPA300.0		AES	

NMOOD Cot o 1 201 District III

Green Analytical Laboratories

ellie Zufett

Debbie Zufelt, Reports Manager

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety. In no event shall Green Analytical Laboratories be liable for incidental or consequential damages. GALs liability, and clients exclusive remedy for any claim arising, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever, shall be deemed waived unless made in writing and received within thirty days after completion of the applicable service.