



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-14-2018 Operator Western Minerals & Oil API # 30-045-21316

Property Name Marron Well No. 5 Location: Unit Section 27 Township 27N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 22 Intermediate -- Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>---</u>	<u>22</u>		
10 min	<u>0</u>	<u>---</u>	<u>22</u>		
15 min	<u>0</u>	<u>---</u>	<u>22</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE --

REMARKS:

Blew down to nothing in 2 seconds

By Bob Chenault

Witness Tarence Arellano

Pumper

(Position)

E-mail address bob@ccinm.com

NMOC
SEP 27 2018
DISTRICT III