



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 9-21-2018 Operator Western Minerals & Oil API # 30-045-23128

Property Name Marron Well No. 5A Location: Unit P Section 27 Township 27N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 16 Intermediate -- Casing 43 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	---	43		
10 min	0	---	43		
15 min	0	---	43		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN PRESSURE** BRADENHEAD 0 INTERMEDIATE --

REMARKS:

Blew down in 1 second

By Bob Chenault

Witness Tarence Arellano

Pumper  
(Position)

E-mail address bob@ccinm.com

NMOC  
SEP 27 2018  
DISTRICT III