OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District111/3distric.htm

## BRADENHEAD TEST REPORT

(Submit I copy to above address)

Date of Test	Aug. 19	2018	Operator M&G Dri	lling Company	AP	1 M30-0 45-35180		
Property Name				1008 Location: Unit			27N Range 08W	
•		. CAIIA.						
Well Status (Shut-In	or brouncing)		Initial PSI: Tubing	6 Intermediate	Vone Casing	Bradenhead		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH								
		PRESSUR	ES:			FLOW CHARACTERISTICS		
TESTING	Braden BH INT	head Csg	INTERM Int Csg		BRADE	NHEAD	INTERMEDIATE	
TIME		8						
5 minutes	0			Steady Flow	-			
10 minutes	0	8		Surges	-			
15 minutes	0	8		Down to Nothing				
20 minutes				Nothing		/		
25 minutes				Gas	_	5000 H		
30 minutes				Gas & Water				
				Water	-			
If bradenhead flowed water, check all of the descriptions that apply below:								
CLEAR FRESH SALTY SULFUR BLACK								
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE								
REMARKS:								
Start test 12:30 pm - 12:50 pm								
1.10								
By Man / Chiness Witness								
P. mail e de		(Position	)					
E-mail address								
					M	MACA		

NMOCD
SEP 27 2018
DISTRICT III