Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.		
					NMSF079060 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
					892000929B 8. Well Name and No.		
1. Type of Well □ Oil Well □ Gas Well ☑ Oil Well □ Gas Well					NEBU 413		
2. Name of Operator BP AMERICA PRODUCTION	BELL		9. API Well No. 30-039-24216-00-S1				
3a. Address3b. Phone I380 AIRPORT RDPh: 970-DURANGO, CO 81303Ph: 970-			(include area code) 2-5997	-5997 10. Field and Pool or Exploratory Area UNDESIGNATED			
4. Location of Well (Footage, Sec., 7			11. County or Parish, State				
Sec 20 T30N R7W NWNE 09 36.802780 N Lat, 107.589279			RIO ARRIBA COUNTY, NM				
12. CHECK THE A	PPROPRIATE BOX(ES) 1	TO INDICA	FE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	□ Acidize		oen	Production (Start/Resume)		UWater Shut-Off	
	□ Alter Casing □ Hy		raulic Fracturing	□ Reclamation		U Well Integrity	
🛛 Subsequent Report	Casing Repair	🗖 New	□ New Construction		olete	🛛 Other	
□ Final Abandonment Notice	Change Plans		and Abandon	Temporarily Abandon			
GP	Convert to Injection	🗖 Plug		U Water I	-		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f BP is submitting the pressure approximately 500 psi, and th degrees F at 3092 feet.	ally or recomplete horizontally, g rk will be performed or provide th d operations. If the operation resu- bandonment Notices must be file inal inspection. test for the NEBU 413 POV	ive subsurface he Bond No. or alts in a multipl d only after all W well. The	locations and measu file with BLM/BIA e completion or reco requirements, includ casing passed a	red and true vo Required sub impletion in a sing reclamation MIT at	rtical depths of all pertin bsequent reports must be new interval, a Form 316 n, have been completed a	ent markers and zones. filed within 30 days 0-4 must be filed once	
See attached MIT chart.							
				NMOCD			
				SEP 1 0 2018			
				DISTRICT III			
14. I hereby certify that the foregoing i	Electronic Submission #43	32842 verifie	d by the BLM We	Il Information	n System		
Comm	For BP AMERICA PRO hitted to AFMSS for processi	DUCTION C	OMPANY, sent to M TAMBEKOU o	o the Farmin n 09/05/2018	gton (18WMT1162SE)		
Name (Printed/Typed) PATTI CAMPBELL			Title REGUL	ATORY AN	ALYST		
Signature (Electronic Submission)			Date 08/27/2	018			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE	4	
Approved By ACCEPTED			WILLIAM TAMBEKOU TitlePETROLEUM ENGINEER Date 09/05/2018				
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to cond	Office Farming	ton					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to m	ake to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED	** BLM RE	VISED ** BLN		0 ** BLM REVISEI	D **	

N. - 5

NMOCDAY

NEBU 413 API # 3003924216 Unit B, Sec. 20, 30N, 07W

POW Survey Report

BP would like to submit pressure test information on the above named well. The casing passed a mechanical integrity test at approximately 500 psi, and the pressure and temperature readings from 8/16/2018 were 35 psia and 101°F at 3092'.

