Form 3160-5			RECEIVE		FOR	M APPROVED	
(June 2015)	UNITED STAT				OMB No. 1004-0137 Expires: January 31, 2018		
BUREAU OF LAND MANAGEME			SEP 0 4 2013		5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELL				NO-O-		G-1312-1823	
	his form for proposals		re-enter an		f Indian, Allottee or Tri	be Name	
	ell. Use Form 3160-3 (A			d Office			
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well					7. If Unit of CA/Agreement, Name and/or No. S Escavada Unit		
☐ Oil Well ☐ Gas Well ☐ Other					Vell Name and No.		
2. Name of Operator					API Well No.		
Enduring Resources IV, LLC 3a. Address	30-043-21320 (include area code) 10. Field and Pool or Exploratory Area						
332 Cr 3100 Aztec, NM 87410 505-636-9743			Rusty Gallup Oil Pool				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1719' FNL & 2352' FWL SEC 26 22N 7W BHL: 2325' FSL & 1815' FEL SEC 22 22N 7W					11. Country or Parish, State Sandoval, NM		
12.	CHECK THE APPROPRIATE B	OX(ES) TO INDI	CATE NATURE O	OF NOTICE, I	REPORT OR OTHER	DATA	
TYPE OF SUBMISSION TYPE OF ACTION							
Acidize					oduction (Start/Resume) Water ShutOff		
	Alter Casing	Hydraulic	Fracturing	Reclamat	mation Well Integrity		
Subsequent Report	Casing Repair	New Con	struction	Recomple	ete	Other INTERMEDIATE CASING	
Final Abandonment Notice	Change Plans	Plug and	Abandon	Temporarily Abandon		<u>ununu</u>	
• 0	Convert to Injection	Convert to Injection Plug Back		Water Disposal			
6×							
completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)			een completed. Final A		Notices must be filed only	after all requirements, including	
		K					
8/29/18 – MIRU. PSI tested 13-3/8 Test blind and pipe rams to 200 psi	" csg to 1500# for 30 min – Good for 10 min (low) and 3000 psi for	Test	annular to 200 ps	si for 10 min (low) and 1500 psi for :	15 min (high). All Test Good.	
12-1/4" Drilling ahead.							
8/30/18- Intermediate TD @ 2719' RIH, w / 66 jts of 9-5/8", 36# J-55, I				ACCE	PTED FOR R	ECORD	
Performed 9 5/8 Cement Job as fol Cement with Halliburton (70% exc		ddad to Laad Vol	ume) 3500 Pri Test	t on Lines Fre	sh Water Spacer @ 8	R# (10 Bbls) followed by Chem	
Wash @ 8.4 # (20 Bbls) , followed	by Fresh Water Spacer @ 8.3 # (10 Bbls) , followe	d by Lead Cement	Mixed @ 12.	3 # YD-2.00, Water 1	0.67 Cal/sx (580 sks/ 207 Bbls Econd	
Cem) followed by Tail Cement Mix Plug @ 04:47 8/231/2018 . Press up						resh H2o Totaling 211 Bbls , Bump Is good cement back to surface , Top	
of Tail 2,169.8 ft , Rig Down Hallibu				FARM	INGTON FIELD	OFFICE	
Enduring Resources will conduct 9	5/8" psi csg test at later date & fil	e on the final casi	ng sundry. 🗸	Ву:	AT		
14. I hereby certify that the forego	ing is true and correct. Name (Pri	nted/Typed)					
Lacey Granillo		Title: Permitting S	necialist				
Kal	6 A			peelanse			
Signature	COPA		Date: 9/4/18				
******	THE SPACE	FOR FEDE	RAL OR STA	TE OFICE	EUSE		
Approved by							
			Title		Date		
Conditions of approval, if any, are	e attached. Approval of this notice	does not warrant					
certify that the applicant holds leg which would entitle the applicant	gal or equitable title to those rights						
Title 18 U.S.C Section 1001 and T any false, fictitious or fraudulent				and willfully	to make to any departm	nent or agency of the United States	

