Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 201

CHAPPY NOTICES AND DEPORTS ON WELLS

5. Lease Serial No. NMSF079003

	NOTICES AND REPORT			NWSF079003		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or	Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agree	ment, Name and/or No.	
1. Type of Well Oil Well ☑ Gas Well ☐ Other				8. Well Name and No. NEBU 211		
2. Name of Operator Contact: PATTI CAMPBELL BP AMERICA PRODUCTION COMPA®-Mail: patti.campbell@bpx.com				9. API Well No. 30-045-26368-00-S1		
3a. Address 3b. Phone No. (included property) 380 AIRPORT RD Ph: 970-712-599 DURANGO, CO 81303 Ph: 970-712-599			le)	10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL WILDCAT FRUITLAND SAND PC		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 27 T31N R7W NENW 1040FNL 1850FWL 36.874756 N Lat, 107.560028 W Lon				SAN JUAN COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICATE NATURE	OF NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	Deepen	☐ Producti	on (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing	g Reclama	tion	■ Well Integrity	
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomp	lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	and Abandon			
6	☐ Convert to Injection	☐ Plug Back	☐ Water D	isposal		
following completion of the involved testing has been completed. Final At determined that the site is ready for f BP is submitting the pressure approximately 500 psi, and the degrees F at 2970 feet.	bandonment Notices must be filed or inal inspection. test for the NEBU 211 POW	nly after all requirements, inclused well. The casing passed	uding reclamation a MIT at	, have been completed an	l-4 must be filed once and the operator has	
See attached MIT chart.	See attached MIT chart.					
				SFP 1 0 20	18	
				DISTRICT 1	H	
14. I hereby certify that the foregoing is				0.1	-	
_		UCTION COMPANY, sent	to the Farming	ton		
	itted to AFMSS for processing					
Name (Printed/Typed) PATTI CA	MPBELL	Title REGU	JLATORY ANA	ALYSI		
Signature (Electronic S	Submission)	Date 08/24/	/2018			
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE US	SE		
Approved By ACCEPT		I TAMBEKOU EUM ENGINE	ER	Date 09/05/2018		
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu		ngton	F			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				ke to any department or a	gency of the United	

NEBU 211

API # 3004526368 Unit C, Sec. 27, 31N, 07W

POW Survey Report

BP would like to submit pressure test information on the above named well. The casing passed a mechanical integrity test at approximately 500 psi, and the pressure and temperature readings from 8/21/2018 were 513 psia and 104°F at 2970'.

