



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCD

OCT 05 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-5-18 Operator Hilcorp Energy Co API #30-0 45-32900
Property Name Salty Dog SWD Well No. 5 Location: Unit 14 Section 16 Township 29 Range 14
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 909 Intermediate 1/A Casing 13 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>-13</u>		
10 min	<u>0</u>		<u>-13</u>		
15 min	<u>0</u>		<u>-13</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/A

REMARKS:

Puff when opened - nothing when
opened after 5 min shut in
Mar 2000/1995

By And Rutas
SWD operator
(Position)

Witness Monica Ruelas

E-mail address _____