



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

DISTRICT III

OCT 12 2018

KNOW

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-11-18 Operator Hilcorp Energy API #30-0 39-23501
Property Name Sunview 30.64 SVD Well No. 1124 Location: Unit 26 Section 26 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 889 Intermediate 0 Casing 12 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	11	0	9
10 min	0	0	10	0	9
15 min	0	0	10	0	9
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

31- Light puff when opened - nothing when
opened after 5 min shut-in. Int light blow to head
at 32 ft. Casing dropping to 8 tubing up to 939

By For Rest
SVD Operator
(Position)

Witness

Monica Trelling
Int nothing when opened after
5 min shut-in

E-mail address _____