

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. RECEIVED NMSF-078883 6. If Indian, Allottee or Tribe Name OCT 02 2018 7. If Unit of CA/Agreement, Name and/or No. Farrington Field Office Canyon Largo Unit Bureau of Land Management 8. Well Name and No. CANYON LARGO UNIT 486
2. Name of Operator Hilcorp Energy Company		9. API Well No. 3003929722
3a. Address 382 Road 3100, Aztec, NM 87410	3b. Phone No. (include area code) 505-599-3400	10. Field and Pool or Exploratory Area BASIN DAKOTA
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface Unit F (SENW), 2420' FNL & 1835' FWL, Sec. 08, T025N, R006W		11. Country or Parish, State RIO ARRIBA, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Interim Reclamation
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company conducted a legacy interim reclamation inpection on 9/13/2018 with BLM Inspector Roger Herrera and received approval for the reclamation BMPs on the subject well.


NMOC
OCT 22 2018
DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Kandis Roland		Title Operations/Regulatory Technician - Sr.
Signature <i>Kandis Roland</i>		Date 10/2/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by <i>Supervisor</i>	Title <i>Supv NMS</i>	Date <i>10/11/18</i>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <i>FFO</i>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RCC Reclamation Completion				Location Name: CANYON LARGO UNIT 486		Date: Revision 3 (3/21/17)							
API#: 3003929722				UL-Sec-Twn-Rng: F 08 025N 006W		Lat/Long: 36.4143, -107.4926 NAD 27							
Surface Owner:				Lease#: NMSF-078883		County/State: RIO ARRIBA, NM							
Pipeline Owner: ENT				Twin/Co-Locate Well Name & Operator:									
Onsite: Dale Crawford		Agency Inspector: 		Contractor:		Seed Mix:							
Interim Reclamation		Completed	Incomplete	Final Reclamation		Completed	Incomplete	N/A	Remediation		Completed	Incomplete	N/A
Have pit sample results been approved				3rd party pipeline removed					Facilities stripped				
Has water been removed from pit				Anchors removed					Certificate of waste issued & approved				
Have pit marker photos been taken				Equipment and piping removed					Depth:				
Has certificate of waste been issued & approved				Power poles removed					Width:				
Have all pit contents been removed				Cathodic protection removed					Length:				
Has sample after content removal been taken				Vegetative cages removed					Date of Excavation Start:				
Is location contoured				CMP's removed					Date of Excavation End:				
Is there 4' of cover over pit				Non native gravel buried or removed					Date of Backfill Start:				
Has top soil been spread evenly				Noxious weeds removed or sprayed					Date of Backfill End:				
Has all non-native gravel been buried or removed				Invasive weeds removed or sprayed					Yards Hauled Out:				
Has pit liner been removed				Contouring complete					Impacted Soil Hauled To:				
Has all trash been removed				Top soil spread					Yards Hauled In:				
Have all weeds been removed				Diversion clean and functional					Fresh Soil Hauled in From:				
Teardrop allows vehicle access to all facilities				Silt trap clean and functional					Approval to backfill				
Drainage ditches allow adequate run off				Cattle guard / gates removed					Back fill mechanically compacted				
All non-traffic areas disked properly				Cellar / mouse hole covered					Facilities reset				
All non-traffic areas seeded				Erosion under control					Trash and debris removed				
Seeded areas have been mulched				Location properly ripped					Close Out Completed				
Noxious weeds have been removed or sprayed				Location properly disked					Soil Removal Sundry Ready to be Filed				
Invasive weeds have been removed or sprayed				Location seeded									
Barriers set to deter traffic				Photo transect installed									
Silt traps are functional				Access road properly closed									
Culverts are functional				Public use controlled									
Upper diversion is functional				Barriers in place									
Erosion under control				Grazing controlled									
Photo transect installed				P&A marker installed & legible									
Have wellhead cages and jersey barriers been removed				Well sign removed									
Have reclamation pictures been taken				Growth at least 70%									
Growth at least 70%				Trash and debris removed from location									
Agency Inspection Date: 9/13/18				Final reclamation photos taken									
Sundry is ready to file				Agency Inspection Date:									
				FAN Ready to be filed									
Comments:				Comments:				Comments:					