State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 10/17/18

Well information:

| API WELL# | Well Name | Well # | Operator Name | Туре | Stat | County | Surf_Owner | UL | Sec | Twp | N/S | Rng | W/E |
|------------------------|-----------------|-----------|-------------------------|------|------|-------------|------------|----|-----|-----|-----|-----|-----|
| 30-045-07256-00- 00 | ANGEL PEAK B | 025 | LOGOS OPERATING, LLC | G | А | San Juan | F | Z | 24 | 28 | Ν | 11 | W |

| Application Type: | |
|--|---|
| P&A Drilling/Ca | sing Change Location Change |
| Recomplete/DHC (For | hydraulic fracturing operations review EPA |
| Underground injection control Gu spudding or initiating recompletio | idance #84; Submit Gas Capture Plan form prior to |
| | |
| Other: Bradenhead re | epair |
| | |

Conditions of Approval:

- Notify NMOCD 24 Hours prior to commencing activities.
- Notify the Agencies of any issues discovered.
- Provide any proposed remediation to the agencies for review and approval prior to beginning remediation.

NMOCD Approved by Signature

10/25/18 Date Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

| | Expires. sundary 51, 2010 | | | | | | | | |
|----|---------------------------|--------------|--|--|--|--|--|--|--|
| 5. | Lease Serial No. | NMSF 047017B | | | | | | | |

| SUNDRY NOTICES AND REPO | | -armin(iio) | 6. If | Indian, Allottee or | Tribe Name | | | | |
|--|--------------------|---|--|--|---|--|--|--|--|
| Do not use this form for proposals to abandoned well. Use Form 3160-3 (A | | PST IF (COMPLETED) IN LICE | | ient | | | | | |
| SUBMIT IN TRIPLICATE - Other instructions on page 2 | | | | 7. If Unit of CA/Agreement, Name and/or No. | | | | | |
| 1. Type of Well | 0 11/ | 9 Wall Name and Na | | | | | | | |
| Oil Well Gas Well Other | | | 8. W | 8. Well Name and No. Angel Peak B 25 | | | | | |
| 2. Name of Operator LOGOS Operating, LLC | | | 9. AI | PI Well No. 30-045 | -07256 | | | | |
| 3a. Address 2010 Afton Place Farmington, NM 87401 3b. Phone No. (include area code) (505) 787-2218 | | | | 10. Field and Pool or Exploratory Area Basin Dakota | | | | | |
| 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) | | | | 11. Country or Parish, State | | | | | |
| 800 FSL & 1700 FWL, SE/SW, N Sec 24 T28N R11W | | | Sa | San Juan County, NM | | | | | |
| 12. CHECK THE APPROPRIATE B | BOX(ES) TO INI | DICATE NATURE | OF NOTICE, R | EPORT OR OTHE | ER DATA | | | | |
| TYPE OF SUBMISSION | | TY | PE OF ACTION | | | | | | |
| ✓ Notice of Intent ☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans | New | en aulic Fracturing Construction and Abandon | Reclamation Recomplete | | Water Shut-Off Well Integrity ✓ Other | | | | |
| Final Abandonment Notice Convert to Injection | | | Water Dist | - | BH Remediation | | | | |
| completion of the involved operations. If the operation results is completed. Final Abandonment Notices must be filed only after is ready for final inspection.) LOGOS requests to perform a Bradenhead Remediation Reference: RBDMS MPK1820056996 NMOCD OCT 23 20 DISTRICT | n per the attach | ed procedure an BLM'S ACTIO OPER AUTH | d current wellbe APPROVAL ON DOES NOT ATOR FROM ORIZATION | ore diagram. OR ACCEPTANO OR RELIEVE THE OBTAINING AN | CE OF THIS LESSEE AND NY OTHER R OPERATIONS | | | | |
| 14. I hereby certify that the foregoing is true and correct. Name (Pr. Marie E. Florez | rinted/Typed) | Regulator | y Specialist | | | | | | |
| Signature Signature | | Title Date | 10/17/2018 | | | | | | |
| THE SPACE | FOR FEDE | ERAL OR ST | ATE OFICE | USE | | | | | |
| Approved by Conditions of approval, if any, are attached. Approval of this notice certify that the applicant holds legal or equitable title to those rights | does not warrant | or | | Da | ite /0/19/18 | | | | |
| which would entitle the applicant to conduct operations thereon. | in the subject lea | ase Office F | 0 | | | | | | |

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Angel Peak B 25 API: 30-045-07256

Angel Peak B 025 Bradenhead Remediation Plan of Action:

- 1. Contract wellhead company to check for secondary seal and replace if testing indicates failure
- 2. If wellhead testing/repair is done, conduct re-test of bradenhead
- 3. If bradenhead gas is not eliminated by wellhead repair, use workover rig for the following:
 - a. Set RBP to conduct casing MIT
 - b. If necessary, run cement bond log and remediate casing



Date Prepared: 10/16/2018 Gomez

Wellbore Schematic

Angel Peak B 25

, m 1

Well Name:

| Location: | | , R11W 800' FSL & 170 | | |
|--|--|-----------------------|--|--|
| County: | San Juan | | Spud Date | |
| API#: | 30-045-07256 Lat 36.642743 Long -107.957782 | | Completion Da | |
| Co-ordinates: | | | Last Workover Da | te: 5/20/2013 |
| Elevations: | GROUND: | 5802' | THE RESIDENCE OF THE PROPERTY | |
| Dontho (KB): | KB: PBTD: | 5812' 6476' | | |
| Depths (KB): | TD: | 6511' | Security and the state of the security of the | |
| | ID. | 0011 | | |
| | All Depths KB | Hole Size | Surface Casing: (9/20/1065) | |
| 1 1 | I I I | 12-1/4" | Surface Casing: (8/20/1965) Drilled a 12-1/4" surface hole to 323'. Set 10 jts 8-5/8", 2 | 144 155 assing at 247! |
| <u>Surface Casing</u> 8-5/8", 24#, J-55 | | 0-323' | Cemented w/ 225 sxs of regular w/ 2%CaCl. Circ cm | |
| 10 jts set at 317' | | 0-323 | Cernented w/ 223 sxs of regular w/ 2 /8CaCi. Circ ciri | to surface. |
| | | | Intermediate Casing: (8/22/1965) | |
| 225 sxs Circ to surface 317' | | TOO at audiens (size) | Drilled a 7-7/8" intermediate hole to 6511'. Set 204 jts 4- | 1/2" 10 5# E5 pasing at 6511" |
| Circ to surface 317 | | TOC at surface (circ) | Stage collars set @ 1912' and 4527'. Cmt stage 1 w/ | |
| | | | w/ 500 cuft of 40% diagel 'D' cmt. Cmt stage 3 w/ 750 | |
| | | | Stage 1 top 5756' (70% calc) 5320'CBL2013, Stage 2 | top 2332' (70%cal) 2300'CBI 2013 |
| | | | Production Casing Liner: | |
| | | 7-7/8" | n/a | |
| | | 323'-6511' | THE STATE OF THE S | |
| | | | Tubing: (5/30/2013) | Length (ft) |
| | | | KB | 10.00 |
| | | | (203) 2-7/8", 6.5# J-55, EUE 8rd tbg jts | 6332.38 |
| | | | (1) Seat Nipple @ 6344' | 1.1 |
| | | | (1) Perf tubing sub | 9.46 |
| | | | | |
| | | | | |
| Intermediate Csg | | 1912' Stage Collar | | |
| 4-1/2", 10.5#, J-55, 204 jts | | TOC @ surface | Set | at: 6353 ft |
| Set at 6511' | | | Rods: | |
| 1650cuft. | | | n/a | |
| Stage collars @ 1912', 4527' | | | | |
| Stage 3 to surface | | | | |
| | | | | |
| | | | Pumping Unit: | 1 |
| | | | n/a | |
| | | | | |
| | | | | |
| | | | Perforations: (9/10/1965) | |
| | | | Lower DK: 1spf from 6380-6400', 6410'-6420' (30 holes) | Sand water frac w/ 20000# 40-60, |
| | | | 5000# 20-40 and 32460 gal H2O. | |
| | | | Upper DK: 1spf 6230-6242', 6254-6260', 6305-6345' (58 | shots) Sand water frac w/ 60000# |
| | | | 20-40 and 25000 10-20 sand and 85510 gal H2O. | |
| Tubing | | | Formations: | |
| 2-3/8" 4.7# J-55 | | | Ojo Alamo- 810' | |
| 203 jts | | | Fruitland- 1508' | |
| EOT at 6353' | | | Pictured Cliffs- 1793' | |
| Seat Nipple at 6344' | | | Lewis- 1840' | |
| | | | Mesaverde- 3350' | |
| | | | Mancus- 4460' | |
| | | | Dakota- 6228' | |
| | | | Morrison- 6504' | |
| | | | Additional Notes: | |
| | | | 2/6/1998- 3 slip stops set | |
| | | | 8/31/1998- Tbg job, 3 bad joints. | |
| | | 45071 Otomo Onllan | 11/13/2010- Isolate csg leak at 202' TIH w/ pkr and prod | equipment. Note pertinent data she |
| | | 4527' Stage Collar | 5/20/2013- RIH w/ CBP @ 6200' log 6200' to surface. Is | |
| | | TOC @2300' | from 230'-40', pump 37 sx class 'G' neat cmp (15.8p | pg), good cmt to surf after 7.5bbl pur |
| | | | confirm top of csg leak from 46-51'. | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| 0 | | Jpper DK: 6230-6345' | | |
| o | | | | |
| o | 1 1 | ower DK: 6380-6420' | | |
| house | | | | |
| | | | | |
| | | | | |
| 6511' | | TOC @ 5300' | | |
| | PBTD - 6476' | | | |
| | TD - 6511' | | | |