

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director
Oil Conservation Division



October 29, 2018

Jodi-Lyn Curtis
HILCORP ENERGY COMPANY
1111 Travis Street
Houston, TX 77002-7002

Re: 2018 Bradenhead Test
Well: Huerfano NP #219, UL I Sec 29 Twn 26N Rge 10W, API # 30-045-20814

Dear Ms. Curtis:

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **November 29, 2018**, and to initiate remedial activity before **January 29, 2019**. Initial Surface Casing psi was 42. Initial Production Casing psi was 71. Five-minute shut-in pressure on Surface Casing was 40.

Gas analysis has been received. Gas appears to be similar on surface casing and production casing.

Reference: RBDMS MPK1830251889 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File