

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director
Oil Conservation Division



October 30, 2018

Dennis Hendrix
Great Western Drilling Co
700 W. Louisiana
Midland, TX 79701-9701

Re: 2018 Bradenhead Test
Well: J E Decker #3A, UL L Sec 8 Twn 32N Rge 11W, API # 30-045-23081

Dear Mr. Hendrix:

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **November 30, 2018**, and to initiate remedial activity before **January 30, 2019**. Initial Surface Casing psi was 54. Initial Production Casing psi was 243. Five-minute shut-in pressure on Surface Casing was 46.

Gas analysis from 2017 appears to show bradenhead and production casing to be the same. Wellbore schematic has been received in 2017. Attempt to fix in June of this year did not work.

Reference: RBDMS MPK1830329004 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File