

State of New Mexico  
Energy, Minerals and Natural Resources Department

---

**Susana Martinez**  
Governor

**Ken McQueen**  
Cabinet Secretary

**Matthias Sayer**  
Deputy Cabinet Secretary

**Heather Riley**, Division Director  
Oil Conservation Division



October 29, 2018

Jodi-Lyn Curtis  
HILCORP ENERGY COMPANY  
1111 Travis Street  
Houston, TX 77002-7002

Re: 2018 Bradenhead Test  
Well: Lucky B LS #12M, UL F Sec 21 Twn 28N Rge 9W, API # 30-045-26563

Dear Ms. Curtis:

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **November 29, 2018**, and to initiate remedial activity before **January 29, 2019**. Initial Surface Casing psi was 34. Initial Production Casing psi was 142. Five-minute shut-in pressure on Surface Casing was 34.

Gas analysis has been received. Gas appears to be similar on surface casing and production casing.

**Reference: RBDMS MPK1830238404 on future correspondence for this issue.**

**Notify the Aztec OCD 24 hours before work is initiated.**

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling  
Deputy Oil and Gas Inspector  
District III - Aztec

CC: Well File