

**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11/12/2018 Operator Hilcorp Energy Company API # 3004507272
Property Name MCCLANAHAN A Well No. 1 Location: Unit M Section 23 Township 028N Range 010W
Well Status Flowing Initial PSI: Tubing 22.8 Intermediate 0 Casing 22.4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	BRADENHEAD			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	0	0	22.3	0	24.9	Steady Flow	
10 min	0	0	23.5	0	25.1	Surges	
15 min	0	0	23.8	0	25.3	Down to Nothing	
20 min	0	0	24.1	0	25.4	Nothing	Y Y
25 min	0	0	24.3	0	25.7	Gas	
30 min	0	0	24.6	0	25.8	Gas & Water	
						Water	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE Bradenhead 0 Intermediate 0

REMARKS:

Tested By gbusiere Witness