District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

# State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 Revised April 3, 2017

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

### Pit, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application

Type of action:  Below grade tank registration  Permit of a pit or proposed alternative of a closure of a pit, below-grade tank, or pit of a pit, below-grade tank, or pit of a mexisting permit of recommendation of an existing permit or recommendation or proposed alternative method	roposed alternative method
Instructions: Please submit one application (Form C-144) per inc	lividual pit, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability shoul environment. Nor does approval relieve the operator of its responsibility to comply with any	
Operator: Enduring Resources, LLC	OGRID #: 372286
Address: _332 Road 3100, Aztec, New Mexico 87410	SED
Facility or well name: Rincon Unit 57	A
API Number: <u>30-039-06732</u> OCD Perm	nit Number:
U/L or Qtr/Qtr A Section 1 Township 26N Rang	
Center of Proposed Design: Latitude 36.5186808 Lon	gitude107.521295 NAD83
Surface Owner: 🛛 Federal 🗌 State 🔲 Private 🗌 Tribal Trust or Indian Allotment	
Temporary: Drilling Workover  Permanent Emergency Cavitation P&A Multi-Well Fluid Manager Lined Unlined Liner type: Thickness mil LLDPE HDI String-Reinforced Liner Seams: Welded Factory Other Volum	PE PVC Other
3. Below-grade tank: Subsection I of 19.15.17.11 NMAC	
Volume: 65 bbl Type of fluid: Produced Water	
Tank Construction material: <u>Steel</u>	
Secondary containment with leak detection   Visible sidewalls, liner, 6-inch li	ft and automatic overflow shut-off
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other	
Liner type: Thicknessmil	
4.  Alternative Method:  Submittal of an exception request is required. Exceptions must be submitted to the S	anta Fe Environmental Bureau office for consideration of approval.
Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary  Chain link, six feet in height, two strands of barbed wire at top (Required if locate institution or church)	
	l l
Four foot height, four strands of barbed wire evenly spaced between one and four	feet

6.	
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	
☐ Screen ☐ Netting ☐ Other	
☐ Monthly inspections (If netting or screening is not physically feasible)	
7.	
Signs: Subsection C of 19.15.17.11 NMAC	
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
☐ Signed in compliance with 19.15.16.8 NMAC	
8.	
<u>Variances and Exceptions:</u> Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.	
Please check a box if one or more of the following is requested, if not leave blank:	
<ul> <li>✓ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval.</li> <li>☐ Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.</li> </ul>	
Exception(s). Requests must be submitted to the Santa Fe Environmental Buleau office for consideration of approval.	
9.	
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptance of the compliance of the complianc	ntable source
material are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	suote source
General siting	
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank.	☐ Yes ☐ No
- NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	□ NA
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit.  NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	☐ Yes ☐ No
adopted pursuant to NMSA 1978, Section 3-27-3, as amended. ( <b>Does not apply to below grade tanks</b> )  - Written confirmation or verification from the municipality; Written approval obtained from the municipality	
Within the area overlying a subsurface mine. (Does not apply to below grade tanks)  - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area. (Does not apply to below grade tanks) - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological	☐ Yes ☐ No
Society; Topographic map	
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	☐ Yes ☐ No
Below Grade Tanks	
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured	
from the ordinary high-water mark).	Yes No
- Topographic map; Visual inspection (certification) of the proposed site	
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;.  - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)	
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.)  - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial	☐ Yes ☐ No
<ul> <li>application.</li> <li>Visual inspection (certification) of the proposed site; Aerial photo; Satellite image</li> </ul>	
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application.  NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No

Within 100 feet of a wetland.  - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit Non-low chloride drilling fluid	
Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).  - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application;  - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet of a wetland.  - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).	☐ Yes ☐ No
- Topographic map; Visual inspection (certification) of the proposed site	☐ Tes ☐ No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.  - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 500 feet of a wetland.  - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
10.  Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 N	IMAC
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached.	
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19. and 19.15.17.13 NMAC	
Previously Approved Design (attach copy of design) API Number: or Permit Number:	
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached.  Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.10 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC	
☐ Previously Approved Design (attach copy of design) API Number: or Permit Number:	

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the	documents are
attached.  ☐ Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC ☐ Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC ☐ Climatological Factors Assessment	
<ul> <li>□ Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>□ Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>□ Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC</li> </ul>	
☐ Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Quality Control/Quality Assurance Construction and Installation Plan	
<ul> <li>□ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC</li> <li>□ Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>□ Nuisance or Hazardous Odors, including H<sub>2</sub>S, Prevention Plan</li> </ul>	
<ul><li>☐ Emergency Response Plan</li><li>☐ Oil Field Waste Stream Characterization</li></ul>	
<ul> <li>☐ Monitoring and Inspection Plan</li> <li>☐ Erosion Control Plan</li> <li>☐ Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC</li> </ul>	
Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.	
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well F Alternative	luid Management Pit
Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems)	
☐ In-place Burial ☐ On-site Trench Burial ☐ Alternative Closure Method	
14.  Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be	attached to the
closure plan. Please indicate, by a check mark in the box, that the documents are attached.  Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)  Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	
15.	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. F 19.15.17.10 NMAC for guidance.	
Ground water is less than 25 feet below the bottom of the buried waste.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).  - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application.  - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	

	☐ Yes ☐ No
Within the area overlying a subsurface mine.  - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area.  - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological	
Society; Topographic map	☐ Yes ☐ No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan by a check mark in the box, that the documents are attached.  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC  Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC  Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17.  Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.  Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC  Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cann Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	.11 NMAC .15.17.11 NMAC
17. Operator Application Certification:	
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and believes	ief.
Name (Print): Title:	
Signature: Date:	
e-mail address:Telephone:	
18.  OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment)  OCD Representative Signature:  Approval Date: 11/2	- 26/B
18. OCD Approval:   Permit Application (including closure plan)   Closure Plan (only)   OCD Conditions (see attachment)	26/B
18.  OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment)  OCD Representative Signature:  Approval Date: 11/2	
18.  OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment)  OCD Representative Signature:  Title: OCD Permit Number:  OCD Permit Number:  19.  Closure Report (required within 60 days of closure completion): 19.15.17.13 NMAC  Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not	
18.  OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment)  OCD Representative Signature:  Approval Date: ///  Title: OCD Permit Number:  Closure Report (required within 60 days of closure completion): 19.15.17.13 NMAC  Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not section of the form until an approved closure plan has been obtained and the closure activities have been completed.	t complete this

22.	
Operator Closure Certification:	
I hereby certify that the information and attachments submitted with this clos belief. I also certify that the closure complies with all applicable closure requ	
Name (Print): Chad Snell	Title: <u>HSE TECH</u>
Signature:	Date: 9/25/2018
e-mail address: <u>csnell@enduringresources.com</u>	Telephone:505-444-0586

### Enduring Resources, LLC Below Grade Tank Closure Report

Lease Name: Rincon Unit #57 API No.: 30-039-06732

Description: Unit A, Section 1, Township 26N, Range 7W, Rio Arriba County

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure requirements of below-grade tanks on Enduring Resources, LLC. (Enduring) locations. This is Enduring's standard procedure for all below-grade tanks. A separate plan will be submitted for any below-grade tank which does not conform to this plan.

### **General Plan**

1. Enduring will close below-grade tanks within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the division requires because of imminent danger to fresh water, public health or the environment.

Closure Date is July 30, 2018

- 2. Enduring will close a below-grade tank that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofitted to comply with Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC.

  Closure Date is July 30, 2018
- 3. Enduring will close a permitted below-grade tank within 60 days of cessation of the below-grade tank's operation or as required by the transitional provisions of Subsection B of 19.15.17.17 NMAC in accordance with a closure plan that the appropriate division district office approves. The closure report will be filed on form C-144.

Required C-144 Form is attached to this document.

4. Enduring will remove liquids and sludge from below-grade tanks prior to implementing a closure method and will dispose of the liquids and sludge in a division-approved facility. Approved facilities and waste streams include:

Envirotech Permit No. NM01-0011 and IEI Permit No. NM 01-0010B Soil contaminated by exempt petroleum hydrocarbons Produced sand, pit sludge and contaminated bottoms from storage of exempt wastes

Basin Disposal Permit No. NM01-005

Produced water

All liquids and sludge were removed from the tank prior to closure activities.

5. Enduring will remove the below-grade tank and dispose of it in a division approved facility or recycle, reuse, or reclaim it in a manner that the appropriate division district office approves.

Enduring has removed the below grade tank, and will dispose of it at a division approved facility, or recycle, reclaim or reuse it in a manner that is approved by the division.

6. Enduring will remove any on-site equipment associated with a below-grade tank unless the equipment is required for some other purpose.

This location is still in production. All other on-site equipment will be utilized in the continued production of oil and gas.

7. Enduring will test the soils beneath the below-grade tank to determine whether a release has occurred. At a minimum 5 point composite sample will be collected along with individual grab samples from any area that is wet, discolored or showing other evidence of a release. Samples will be analyzed for BTEX, TPH and chlorides to demonstrate that the benzene concentration, as determined by EPA SW-846 methods 8021B or 8260B or EPA method that the division approves, does not exceed 0.2 mg/kg; total BTEX concentration, as determined by EPA SW-846 methods 8021B or 8260B or other EPA method that the division approves, does not exceed 50 mg/kg; the TPH concentration, as determined by EPA method 8015M or other EPA method that the division approves, does not exceed 100mg/kg; and the chloride concentration, as determined by EPA method 9056A or other EPA method that the division approves, does not exceed 250 mg/kg, or the background concentration, whichever is greater. Enduring will notify the division of its results on form C-141.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached). Sampling was witness by Cory Smith, NMOCD Aztec.

Components	Test Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	0.00153 mg/kg
BTEX	EPA SW-846 8021B or 8260B	50	0.10653 mg/kg
TPH	EPA SW-846 8015M	100	176.05 mg/kg
Chlorides	EPA 9056A	250 or background	251 mg/kg

8. If Enduring or the division determines that a release has occurred, Enduring will comply with 19.15.3.116 NMAC and 19.15.1.19NMAC as appropriate.

Release had occurred due to a leak formed in the bottom allowing some residual water to be released. Approximately 3CY of impacted soil was removed and a sample was collected. Returned samples are below the closure requirements for this location.

9. If the sampling program demonstrates that a release has not occurred or that any release does not exceed the concentrations specified in Paragraph (4) of Subsection E of 19.15.17.13 NMAC, Enduring will backfill the excavation with compacted, non-waste containing, earthen material; construct a division prescribed soil cover; recontour and re-vegetate the site.

The site has been backfilled, and will be recontoured and revegetated upon P&A of the wellsite.

- 10. Notice of Closure operations will be given to the Aztec Division District III office between 72 hours and one week prior to the start of closure activities via email or verbally. The notification will include the following:
  - i. Operator's name
  - ii. Well Name and API Number
  - ii. Location by Unit Letter, Section, Township, and Range

Notification was provided to Mr. Cory Smith with the Aztec office of the OCD via email on July 23, 2018; see attached email printout.

The surface owner shall be notified of Enduring's proposal to close the BGT as per the approved closure plan using certified mail, return receipt requested.

The BLM was notified on July 23, 2018 via email; see attached email printout.

11. Re-contouring of location will match fit, shape, line, form and texture of the surrounding area. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be placed in areas where needed to prevent erosion on a large scale. Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

This site will be recontoured and revegitated once plugging and abandoning activities have been completed. The site will be recontoured to match the above mentioned specifications.

12. A minimum of 4 feet of cover shall be achieved and the cover shall include 1 foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

The area has been backfilled to match these specifications.

13. Enduring will seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will be used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

The site will be re-seeded per the BLM specifications once plugging and abandoning activities have been completed.

- 14. All closure activities will include proper documentation and be available for review upon request and will be submitted in closure report form to OCD within 60 days of closure of the below-grade tank. Closure report will be filed on form C-144 and incorporate the following:
  - Proof of closure notice to division and surface owner; attached
  - Details on capping and covering, where applicable; per OCD Specifications
  - Confirmation sampling analytical results; attached
  - Disposal facility name(s) and permit number(s); attached
  - Soil backfilling and cover installation; per OCD Specifications
  - Re-vegetation application rates and seeding techniques, (or approved alternative to re-vegetation requirements if applicable); **pursuant to BLM Specifications**
  - Photo documentation of the site reclamation. attached

### **James McDaniel**

From: James McDaniel

**Sent:** Monday, July 23, 2018 5:01 PM

To: 'Smith, Cory, EMNRD'; Fields, Vanessa, EMNRD

Cc: 'Thomas, Leigh'; Chad Snell

Subject: Rincon Unit 57 and 80 BGT Closures

### Too all concerned parties,

Please accept the following email as the required notification for BGT closure activities being performed on the following well sites:

Rincon 57 – API 30-039-06732 Section 1, Township 26N, Range 7W, Rio Arriva County, NM

Rincon 80 – API 30-039-07086 Section 18, Township 27N, Range 6W, Rio Arriba County, NM

Both pits are being closed for maintenance upgrades.

Closure activities will be performed on Monday, July 30<sup>th</sup> at 9:00 AM at the Rincon 57, then the crew will mobilize to the Rincon 80 immediately following sampling at the Rincon 57. Thank you for your time in regards to this matter.

James McDaniel HSE Supervisor Enduring Resources CSP #30009 CHMM #15676 Office: 505-636-9731 Cell: 505-444-3004

imcdaniel@enduringresources.com



Mr. Cory Smith
Oil Conservation Division
1000 Rio Brazos Rd.
Aztec, New Mexico 87410
Email: cory.smith@state.nm.us
Phone (505) 334-6178 Ext 115

Re: Variance Request for 19.15.17 NMAC Table I and Table II

Mr. Smith,

Please accept this letter as a variance request as outlined in 19.15.17.15(A) NMAC. Enduring Resources, LLC (Enduring) would like to request the replacement of USEPA Method 418.1 for the analysis of Total Petroleum Hydrocarbons (TPH) for USEPA Method 8015M, measuring carbon ranges C6-C36, for all sampling associated with closures and confirmations samples in relation to 19.15.17 NMAC, both in Table I and Table II (2103) and the 'pit rule' passed in 2008. Enduring is requesting this variance on the grounds that USEPA Method 418.1 is an outdated analytical method that reports a full range of hydrocarbons from C5 through C40 (*Reference: American Petroleum Institute*).

The attached table demonstrates the carbon ranges, and the typical hydrocarbon products that can be found in those ranges. As you can see, lube oil ranges from C28-C35. Analytical Method USEPA 418.1 extends past lube oils from C35 through C40. This range of hydrocarbons is above the range that can reasonably be expected to be found in our field in both drilling pits and beneath below grade tanks. USEPA Method 8015M (GRO/DRO + extended analysis) will report hydrocarbons ranging from C6-C10 for GRO, C10- C28 for DRO, and C28-C36 for extended analysis. This information was provided by Environmental Science Corporation Laboratories. As the information demonstrates, the 8015M analytical method reports as low as C6, reporting lower than USEPA Method 418.1. Utilizing analytical method 8015M, lighter range hydrocarbons will be reported instead of higher range, heavy hydrocarbons that may not be reasonably expected to be found in our field. Utilization of USEPA Method 8015M will better protect groundwater resources by identifying lighter, more mobile hydrocarbons that USEPA Method 418.1 cannot identify. The heavier range hydrocarbons, C36-C40, that are not identified by USEPA Method 8015M are not a mobile form of hydrocarbon, and are not a threat to human health and the environment. With your acceptance of this variance request, Enduring Resources will begin utilizing USEPA Method 8015M in place of USEPA Method 418.1 for all sampling activities associated with 19.15.17 NMAC, both from the rules passed in 2008 and 2013.

Respectfully Submitted, James McDaniel, CHMM #15676 HSE Supervisor Enduring Resources, LLC

### Carbon Ranges of Typical Hydrocarbons

Hydrocarbon Carbon Range
Condensate C2-C12
Aromatics C5-C7
Gasoline C7-C11
Kerosene C6-C16
Diesel Fuel C8-C21
Fuel Oil #1 C9-C16
Fuel Oil #2 C11-C20
Heating Oil C14-C20
Lube Oil C28-C35



### Enduring Resources, LLC BGT Closure Report Rincon Unit 57 30-039-06732

PHOTOS: New Above Grade Tank Set







# ANALYTICAL REPORT

August 08, 2018

### **Enduring Resources**

Sample Delivery Group:

L1014207

Samples Received:

08/02/2018

Project Number:

Description:

**BGT Closure** 

Site:

**RINCON UNIT 57** 

Report To:

James McDaniel

332 County Road 3100

Aztec, NM 87410

Entire Report Reviewed By:

Olivia Studebaker

Project Manager

Results relate only to the items tested or calibrated and are reported as rounded values. This test report shall not be reproduced, except in full, without written approval of the laboratory. Where applicable, sampling conducted by Pace National is performed per guidance provided in laboratory standard operating procedures: 060302, 060303, and 060304.

### SAMPLE SUMMARY

Collected by

ONE LAB. NATIONWIDE.

Received date/time

Collected date/time

mad	
200	
-	

BGT BOTTOM L1014207-01 Solid			Chad Srell	08/01/18 09:50	08/02/18 08:45
Method	Batch	Dilution	Preparation	Analysis	Analyst
			date/time	date/time	
Total Solids by Method 2540 G-2011	WG1148414	1	08/07/18 12:38	08/07/18 12:50	JD
Wet Chemistry by Method 9056A	WG1147229	1	08/03/18 11:30	08/03/18 19:52	MCG
Volatile Organic Compounds (GC) by Method 8015/8021	WG1147160	1	08/02/18 19:49	08/03/18 19:15	LRL
Semi-Volatile Organic Compounds (GC) by Method 8015	WG1147714	1	08/04/18 10:13	08/04/18 18:44	AAT


















### **BGT BOTTOM**

### SAMPLE RESULTS - 01

ONE LAB. NATIONWIDE.

1101420




### Total Solids by Method 2540 G-2011

	Result	Qualifier	Dilution	Analysis	Batch
Analyte	%			date / time	
Total Solids	85.1		1	08/07/2018 12:50	WG1148414







	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch
Analyte	mg/kg		mg/kg		date / time	
Chloride	251		11.8	1	08/03/2018 19:52	WG1147229



### Volatile Organic Compounds (GC) by Method 8015/8021

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
Benzene	0.00153		0.000588	1	08/03/2018 19:15	WG1147160	
Toluene	ND		0.00588	1	08/03/2018 19:15	WG1147160	
Ethylbenzene	ND		0.000588	1	08/03/2018 19:15	WG1147160	
Total Xylene	0.105		0.00176	1	08/03/2018 19:15	WG1147160	
TPH (GC/FID) Low Fraction	3.25		0.118	1	08/03/2018 19:15	WG1147160	
(S) a,a,a-Trifluorotoluene(FID)	96.2		77.0-120		08/03/2018 19:15	WG1147160	
(S) a,a,a-Trifluorotoluene(PID)	96.7		75.0-128		08/03/2018 19:15	WG1147160	





# 9Sc

### Semi-Volatile Organic Compounds (GC) by Method 8015

	Result (dry)	Qualifier	RDL (dry)	Dilution	Analysis	Batch	
Analyte	mg/kg		mg/kg		date / time		
C10-C28 Diesel Range	114		4.70	1	08/04/2018 18:44	WG1147714	
C28-C40 Oil Range	58.8		4.70	1	08/04/2018 18:44	WG1147714	
(S) o-Terphenyl	66.5		18.0-148		08/04/2018 18:44	WG1147714	

### WG1147229

### QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

### L1014207-01

### Method Blank (MB)

Chloride

Wet Chemistry by Method 9056A

 MB R3330948-1
 08/03/18 19:00
 MB Result
 MB Qualifier
 MB MDL
 MB RDL

 Analyte
 mg/kg
 mg/kg
 mg/kg

 Chloride
 U
 0.795
 10.0





### L1014209-01 Original Sample (OS) • Duplicate (DUP)

(OS) L1014209-01 08/03/18 20:18 • (DUP) R3330948-6 08/03/18 20:27

Original Result (dry) Dilution DUP RPD DUP Qualifier (dry) DUP RPD wights

Analyte mg/kg mg/kg %

55.5




## Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

4.11

(LCS) R3330948-2 08/03/18 19:09 • (LCSD) R3330948-3 08/03/18 19:17

53.3



15



GI

### Sc

### L1014207-01 Original Sample (OS) • Matrix Spike (MS) • Matrix Spike Duplicate (MSD)

(OS) L1014207-01 08/03/18 19:52 • (MS) R3330948-4 08/03/18 20:01 • (MSD) R3330948-5 08/03/18 20:10

	Spike Amount (dry)	Original Result (dry)	MS Result (dry)	MSD Result (dry)	MS Rec.	MSD Rec.	Dilution	Rec. Limits	MS Qualifier	MSD Qualifier	RPD	RPD Limits
Analyte	mg/kg	mg/kg	mg/kg	mg/kg	%	%		%			%	%
Chloride	588	251	844	793	101	92.3	1	80.0-120			6.19	15

### WG1147714

### QUALITY CONTROL SUMMARY

ONE LAB. NATIONWIDE.

L1014207-01

### Method Blank (MB)

(MB) R3330969-1 08/04/18 17:28 MB Result MB MDL MB RDL MB Qualifier mg/kg mg/kg Analyte mg/kg C10-C28 Diesel Range U 1.61 4.00 C28-C40 Oil Range U 0.274 4.00 (S) o-Terphenyl 92.4 18.0-148

Semi-Volatile Organic Compounds (GC) by Method 8015









### Laboratory Control Sample (LCS) • Laboratory Control Sample Duplicate (LCSD)

(LCS) R3330969-2 08/04/	/18 17:41 • (LCSI	D) R3330969-3	3 08/04/18 17:5	54						
	Spike Amount	LCS Result	LCSD Result	LCS Rec.	LCSD Rec.	Rec. Limits	LCS Qualifier	LCSD Qualifier	RPD	RPD Limits
Analyte	mg/kg	mg/kg	mg/kg	%	%	%			%	%
C10-C28 Diesel Range	50.0	39.0	39.4	78.1	78.8	50.0-150			0.966	20
(S) o-Terphenyl				96.0	88.6	18.0-148				









			the 1 s	Mani		1 1			Analys	is / Container	/ Preserva	rive		The Asset	
		В	illing Inform	ation:				10.5							
Enduring Resources			ames McI	Daniel	Pres	ad C	ns to	56							
iddi.iig				y Road 3100		4								LAB S.C.	E.N.C.E.S
2 County Road 3100			Aztec, NM											- 616	sistery of Freezewitten
tec, NM 87410														12065 Lebanon Rd	回來習回
too, till or			Email To:			1		-						Mount Juliet, TN 37122 Phone: 615-758-5658	
part to:		1	T 4- /-	n'el@endu	ine tresur	C+500		9						Phone: 800-767-5859 Fax: 615-758-5859	
James McDan	el		Jracas	City/State	-			SR							1.7
oject				Collected:		3		11					14	LA L1014	101
scription: BGT Closure			Lab Project #					9						E114	
none: 505-636-9731	Client Project #					1		E							
X:						4	~	13						Acctnum: ENDE	RESANM
	Site/Facility ID	#		P.O. #		THE STREET	BIEX	3	- 1	Constant of				ASSESSMENT OF THE PARTY OF THE	
flected by (print):	Rincon		57			-	1	600	U					Template:	
Chad Snell	Puch2 II	ab MUST Be 1	Notified)	Quote #			12	10	5					Prelogin:	as Diebarde
oilected by (signature):	Same Da	y Five D	ay		-		1	-					TSR: 288 - Daph	ne rucharus	
Car 8	Alout Pro	5 Day	(Rad Only)	Date Resul	ts Needed	No.	2	M	X					PB:	
nmediately	Two Day	10 Da	y (Rad Only)		,X	of	O	8065	16					Shipped Via:	
acked on Ice N Y <u>X</u>	Three Di	1		0.11	Time	Cntrs	80	10	Milosia					Remarks	Sample # (lab only)
Sample 1D	Comp/Grab	Matrix *	Depth	Date			-	V	X				ī		-01
2 1:	0	35	-	8-1-2018	9:50 a	m /.	X	X	A						
BGT Bottom.	Cong	1			19 July 19	Conce									
			- The company		-	-11									100
															Local Control
		1													
		-	-		-										
													42		
					1										
			_												
						-							E15		
					1							A CONTRACTOR OF THE PARTY OF TH		Sample Peccipt	Checklist
	Domaska				the same and					рН	Tem	p	COC S	sal Present/Intac igned/Accurate:	1
* Matrix: SS - Soil AIR - Air F - Filter	Remarks:												Wash to Day	en arrive intact ct hottles used:	STATE OF THE PARTY
GW - Groundwater B - Bioassay										Flow	Oth	er	Suffi	人人也也是一位的工程的唯一可是D	Delication of the second
ww - WasteWater		toward stay				0							THE RESIDENCE	1f Applac	<b>西瓜太陽</b>
DW - Drinking Water	Samples re	FedExC	Courier		Tracking # (	4190	0 3	260	176	Trip Blank R	lacabinet 1	(as / (an)	Prese	ero Headapace: rvation Correct/	Checked: Y
OT - Other					Received by:					Trip Blank B	(eceived:	HCL/MeoH		5MR/HR	
Relinquished by : (Signature)		Date:	2.10	111112								TAR		servation required by	Login: Date/Time
Phily		8-1	-2018	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO I	Received by:	Signatur	e)		\$70-1-100 may	Temp:	*C 80	ttles Received:	if pres	servation required by	
Relinquished by : (Signature)		Date.		Time	neceived by.					0.6	7	1			- Loudina
Henrichanism al , (a.B					5.1			5186		Date:	TI	me:	Hold:		NCF / C
		Date:		Time:	Received for	lab by: (5	agnatur	THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.				co			
Refinquished by : (Signature)					1-11	-		8	Gl	8/2/18	8	45	TOTAL STREET		and the second second