



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOC

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OCT 17 2018
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-16-18 Operator Great Western API #30-0 45-23081

Property Name E Decker Well No. 3A Location: Unit 4 Section 8 Township 32 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 100 Intermediate 1/A Casing 243 Bradenhead 54

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	7		243		
10 min	7		243		
15 min	7		243		
20 min	7		243		
25 min	7		243		
30 min	7		243		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	☒	
Surges		
Down to Nothing		
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 46 INTERMEDIATE 1/A

REMARKS: Hard blow when opened for full 30 minute test - previous
my work did not fix problem -
No API # on well Design or footage

By C. S. Satcher
(Position)

Witness Monica Kuehling

E-mail address _____