



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 12-11-2018 Operator Hilcorp Energy Co. API # 30-0 45-26239

Property Name Huerfano Unit Well # 180E Location: Unit N Sec 18 Twn 26 Rge 9

Land Type:

State _____
Federal X
Private _____
Indian _____

NMOCD
DEC 12 2018
DISTRICT III

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (N): Post Workover TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 1
Int. Casing Pres. _____

Pressured annulus up to 570 psi. for 30 mins. Test passed/~~failed~~

REMARKS: Pressured up to 570psi - Had Drop to 565psi at 10min -
Slight drop to 560psi at 20min - 555psi for end of test

By Witnessed by Ralf Sloan
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02