



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-26-18 Operator Maralex API #30-0 45-2898
Property Name TAK Well Well No. 1 Location: Unit Section 7 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 25 Intermediate NA Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		25		
10 min	0		25		
15 min	0		25		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

BH through 1" Fittings, nothing

By Eric Crow
Mechanic
(Position)

Witness

E-mail address

NMOC
DEC 10 2018
DISTRICT III