

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://omnrd.state.nm.us/ocd/District N/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-26-18 Operator	Maralex API #30-045-34080
Property Name Dome Fed. 17 Well No. 17	Location: UnitSection/7_Township27_Range/7
Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate NA Casing 20 Bradenhead 0	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 / 70 \	Steady Flow
10 min 0 20	Surges
15 min 20	Down to Nothing
20 min	Nothing
25 min	Gas
30 min /	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE MA	
REMARKS: BH through 2 pipe, withing	
By Tic Crfw Witness	
Mechanic (Position)	
E-mail address	

