RECEIVED

Form 3160-5 (June 2015)	UNITED STATES DEPARTMENT OF THE IN		DEC 17	2018	FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018				
BUREAU OF LAND MANAGEMENT				14 046-	5. Lease Serial No.				
Do not use thi	Y NOTICES AND REPOR is form for proposals to II. Use Form 3160-3 (API	drill or to	o re-enter an	lanagem	6 If Indian, Allottee	or Tribe Name	à		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well					N/A				
Oil Well Gas Well Other					8. Well Name and N	O. Marcus A#	3		
2. Name of Operator DJR Operating, LLC					9. API Well No. 30-039-23851				
3a. Address 1 Road 3263, Azte	(include area cod	le)	10. Field and Pool or Exploratory Area						
	6 Counselors			Gallup Dakota					
4. Location of Well (Footage, Sec.,		11. Country or Parish, State							
600 FNL, 600 FWL, D-Sec. 17-T23N, R6W				Rio Arriba County, New Meixco					
12. C	THECK THE APPROPRIATE BOX	(ES) TO INI	DICATE NATURI	E OF NOTI	CE, REPORT OR OT	THER DATA			
TYPE OF SUBMISSION	TYPE OF AC				CTION				
Notice of Intent	Acidize	Deep		Produ	uction (Start/Resume)	Water	r Shut-Off		
	Alter Casing	Hydr	aulic Fracturing	✓ Recla	amation	Well	Integrity		
Subsequent Report	Casing Repair	New	Construction	Reco	mplete	Other			
	Change Plans	Plug	and Abandon	Temp	orarily Abandon				
Final Abandonment Notice	Convert to Injection	Plug	Back	Water	r Disposal				
completion of the involved oper completed. Final Abandonment is ready for final inspection.)	will be performed or provide the Be ations. If the operation results in a Notices must be filed only after all and abandoned on 6-29-2018.	multiple com	pletion or recomp	oletion in a r	new interval, a Form	3160-4 must be	e filed once testi	ing has bee	
On 12-13-18, Robert Switze	or of the BLM-FFO and Paul Leh Meter Run and all above ground								
The site has been re-contou	red, reseeded and all other spec	cified requir	ements per the	Reclamatio	on Plan as approved	by the BLM-	FFO.		
Per Robert Switzer, BLM-FF	FO AO, the site has been found t	to comply w	ith the interim re	quirement	s under the BLM gu	Column or Share to company or or company	and annual of the latest and the lat	on Plan.	
Final Reclamation/FAN will t	be forthcoming as the site meets	BLM final	eclamation veg	etation star	ndards.	NMOC	D		
Pictures taken of the interim reclamation are attached hereto for reference.						DEC 2 1	2018		
						STRICT	111	-	
4. I hereby certify that the foregoing	g is true and correct. Name (Printed	d/Typed)							
Paul Lehrman 1			Landman Title						
Signature	Date 12/17/2018								
	THE SPACE F	OR FEDE	RAL OR ST	ATE OF	CE USE				
approved by						UEU	1 7 201	10	
Accepted for Record			Title			Date	' '	10	

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



Office

Attached to Sundry for Interim Reclamation Approval dated 12-17-18.

MARCUS A #3

Surface:

Federal

Minerals:

Federal

Lease No.

SF-078359

Lease No. 3F-076

API #: 3003923851 **Well Name:** MARCUS A # 003

Location: D-17-23.0N-06N, 600 FNL, 600 FWL Lat:36.2305201691 Long: -107.499255365

Operator Name: DJR OPERATING, LLC County: Rio Arriba

Land Type: Federal Well Type: Oil Spud Date: 9/22/1982 Plug Date:

Elevation GL: 6882 Depth TVD: 5635

Pools associated:

COUNSELORS GALLUP-DAKOTA Total Acreage: 160.00




Photo Taken 12-13-2018. Interim Reclamation October 2018.

Looking West along access road from main road to pad entrance. Note barrier fence.



Photo Taken 12-13-2018. Interim Reclamation October 2018. Looking West along access road.




Photo Taken 12-13-2018. Interim Reclamation October 2018.

Looking Westerly from NE Corner of Pad.




Photo Taken 12-13-2018. Interim Reclamation October 2018.

Looking Due West from NW corner of Pad.




Photo Taken 12-13-2018. Interim Reclamation October 2018.

Looking Northwest from SE corner of pad. Showing re-contouring of pad to north.