



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

DEC 12 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-11-18 Operator Hilcorp Energy API #30-0 45-08511
Property Name Lucky A Well No. 2 Location: Unit 12 Township 29 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 96 Intermediate N/A Casing 105 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>106</u>		
10 min	<u>0</u>		<u>106</u>		
15 min	<u>0</u>		<u>106</u>		
20 min	<u>0</u>		<u>106</u>		
25 min	<u>0</u>		<u>106</u>		
30 min	<u>0</u>		<u>106</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing when opened - Nothing when opened
after 5 min shut in

By Daniel Hader

Witness Mona Kuchler

(Position)

E-mail address _____