



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

MAR 14 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 3/14/2019 Operator Hilcorp Energy API #30-0 45-20992
Property Name Mansfield Well No. 11 Location: Unit N Section 29 Township 30 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 561 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>560</u>			
10 min	<u>0</u>	<u>559</u>			
15 min	<u>0</u>	<u>557</u>			
20 min	<u>0</u>	<u>552</u>			
25 min	<u>0</u>	<u>550</u>			
30 min	<u>0</u>	<u>547</u>			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

BH light puff, had layer of ice on valve. BHT ran during MFT

By Joe McElharris

Witness Garrett D Kelly

(Position)

E-mail address _____