



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm>

NMOCd

APR 15 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-12-19 Operator Hilcorp Energy Co API #30-0 39-26967
Property Name San Juan 28744 Well No. 233R Location: Unit 14 Section 14 Township 28 Range 7
Well Status (Shut-In) or Producing) Initial PSI: Tubing 94 Intermediate 0 Casing 95 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	96	0	96
10 min	0	0	96	0	96
15 min	0	0	96	0	96
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		✓
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Puff when opened. Nothing when opened after 5 min shut in. Int. (Nothing when opened. Nothing when opened after 5 min shut in)

By Mark E. Goodwin

Witness Monica Cuckling

(Position)

E-mail address _____