



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

# BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 17 APR 2019 Operator HILCORP API #30-0 39-21732  
Property Name SAN JUAN 28-7 Well No. 110 Location: Unit K Section 12 Township 27 Range 7  
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 580 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	N/A	580		
10 min	0		570		
15 min	0		560		
20 min	0		550		
25 min	0		550		
30 min	0		550		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADEN HEAD AND NOTHING CAME OUT

By

(Position)

Witness

NMOCB

APR 17 2019

DISTRICT III

E-mail address \_\_\_\_\_