



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 22-APR-2019 Operator HL CORP API #30-0 39-23855

Property Name SAN JUAN 28-5 Well No. 1026 Location: Unit 0 Section 12 Township 28 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 109 Intermediate 1 Casing 112 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	112	0	113
10 min	0	1	112	0	113
15 min	0	1	112	0	113
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		X
Nothing	X	
Gas		X
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

OPENED THE BRADEN HEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT FLEW DOWN TO NOTHING
IN 1 MINUTE

By Danny T. G. Ito

Witness [Signature]

(Position)

E-mail address _____

NMOC

APR 23 2019

DISTRICT III