



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

NMOC

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

17 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-17-19 Operator Southland Royalty Co LLC API #30-0 39-26868

Property Name Cuison SW Well No. 1 Location: Unit D Section 26 Township 30 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 4 Intermediate 0 Casing -8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	-8	0	-8
10 min	0	0	-8	0	-7
15 min	0	0	-8	0	-7
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Nothing when opened - Nothing when opened after 5 min shut in - Int - blow through needle valve to clear at 1 min 19 seconds. Nothing when

By Dakota McAdams

Witness Monica Kuehn

opened after 5 min shut in

(Position)

E-mail address _____