



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 4-18-19 Operator Synergy Op LLC API # 30-0 43-20981

Property Name Boisd'Arc Well # 1 Location: Unit I Sec 22 Twn 21 Rge 5

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

111 DISTRICT 111
APR 18 2019
NMOCD

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. Y/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 1184

Pressured annulus up to 550 psi. for 30 mins. Test passed/failed

REMARKS:

Dropped to 542 and held


Top Ref = 5920 - 4093
Packet Set = 5850

By [Signature] 4-18-19
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02



DISTRICT III

APR 18 2018

MMOCD

Synergy

CHART NO. MC MP-1000-1HR
WS1 Orlando

METER

TAKEN OFF

CHART PUT ON

LOCATION

REMARKS

Bowed arc divide SWD #1

Cosmy test 0-550 ps
30min

Mentor Technology
Orlando
4-18-19