

## NEW MIEXICO EMERGY, MINIERALS & NATURAL RESOURCES IDEPARTMIENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 4/23/19 Operator_ENDURING RESOURCES IV LLC_API #30-039-06683	
Property Name: RINCON UNIT Well No: 051 Location: Unit L Section 06 Township 26N Range 06W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 28 Intermediate V/A Casing 29 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 8 29	Steady Flow
10 min 30	Surges
15 min 29	Down to Nothing
20 min 29	Nothing
25 min 29	Gas
30 min 29	Gas & Water
/	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE VI	
REMARKS:	
	NNOCD
	MAY 0 2 2019
By John Dockter Wi	tnessDISTRICT
HSE Tech	
(Position)	
E-mail address Docker Enduring Resources, Com	