



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 27-Apr-2019 Operator HIL CORP API #30-0 391-070 36
Property Name SAN JUAN 287 Well No. 109 Location: Unit _____ Section _____ Township _____ Range _____
Well Status(Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing 590 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME	0	N/A	590		
5 min	0		590		
10 min	0		585		
15 min	0		580		
20 min	0		580		
25 min	0		580		
30 min	0		580		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By [Signature]
Co. Rep.
(Position)

Witness [Signature]

E-mail address _____

III DISTRICT III
APR 29 2019
NMOC