



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test APR-2019 Operator HILCORP API # 30-0 31-07-0246

Property Name SAN JUAN 28-7 Well # 107 Location: Unit 18 Sec 18 Twn 27 Rge 7

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. Tbg. SI Pres. Max. Inj. Pres.
Cradenhead Pres. Tbg. Inj. Pres.
Tubing Pres.
Int. Casing Pres.

Pressured annulus up to psi. for mins. Test passed/failed

REMARKS: 100 PSI SPRING, 60 MINUTE LEAK RBP SET 5140
THE Casing WAS PRESSURED UP TO 590 PSI AND PRESSURE
FELL TO 580 PSI AND PRESSURE HELD FOR THE LAST 15 MINUTES

by [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

[Signature]
(Position)

NMOCD

APR 29 2019

Revised 02-11-02

DISTRICT III