

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT (Submit 2 copies to above address)						
Date of Test	4-22-19	Operator	Logos Operating,		NPI # 300	4534945
	(Well Nar ut-in or Producing)	DER COM 201S ne and Number) Tubing	Location: Unit B	/ 4_ Casing <u>57</u>		ead <u>À</u>
Time 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes 5 minute SI	Bradent BH Casing Monito O 562 O 562 O 562 O 562	ead Intermediate Monitor	Intermediate Intermediate Blowdown Monitor	Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water	Bradenhead Flowed	
Clear 5 Minute S REMARKS:	hut-in Bradenhe	Sal	Intermediate <u>N/A</u>	Blad	NMOCD PR 2 6 2019 Irict III	-
By <u>Lugo</u> Brodu	ne Burban	k m	Witness/	I-ul-	- NMOLD	