

NEW MEXICO ENERGY, MINIERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-12-19 Operator Rim UP ERATING- INCAPI #30-0 39 - 22700				
Property Name G-REVEY	Well No/	_Location: Unit	t & Section /	<u>¶</u> Township <u>26</u> Range <u>7ω</u>
Well Status(Shut-In or Producing) Initial PSI: Tubing $\nu \not \mid A$ Intermediate $\nu \not \mid A$ Casing 12 Bradenhead 0				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
Testing Bradenhead BH Int Csg TIME	E INTERM Int Csg	BR	FLOW CHA	RACTERISTICS INTERMEDIATE
5 min 0 12		Steady Flow		
10 min U /2		Surges		
15 min <i>D</i> 12		Nothing Nothing		
25 min		Gas		1
30 min_		Gas & Water		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH_	SALTY	SULFURE	BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD D INTERMEDIATE M/A REMARKS:				
By Steven Maria Witness		ness		NMOCD
(Position)				111/10/2013
E-mail address				DISTRICT III