



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-29-19 Operator: Enervest Operating, LLC API # 30-039-24123 ✓

Property Name: Bear Canyon Well No. 01 Location: Unit G Section: 15 Township: 26N Range: 2W ✓

Well Status (Shut-In or Producing) Initial PSI: Tubing 49 Intermediate N/A Casing 49 Bradenhead 49

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>49</u>		<u>49</u>		
10 min	<u>49</u>		<u>49</u>		
15 min	<u>49</u>		<u>49</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>49</u>	
Nothing	<u>49</u>	
Gas	<u>49</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 49

INTERMEDIATE N/A

REMARKS:

Shut off PS & Compressor performed test, no flow, dead
Nothing after 5 min SI

By

Robert Cantrell
Operator

(Position)

Witness _____

E-mail address _____

NMOCD

MAY 09 2019

DISTRICT III