



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III/district.htm](http://emrdd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-10-2019 Operator Rim OPERATING API #30-0 39-29215

Property Name ELK com 10 Well No. 1B Location: Unit B Section 10 Township 25N Range 2W

Well Status(Shut-In or Producing) Initial PSI: Tubing 190 Intermediate Casing 220 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>220</u>		
10 min	<u>0</u>		<u>220</u>		
15 min	<u>0</u>		<u>220</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Tony Schmitz

Witness

WM000

LEASE OPERATOR
(Position)

E-mail address tschmitz2@rimop.com

DISTRICT III