



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 1-JUNE 2019 Operator HILCOARD API # 30-0 39-07114

Property Name SAN JUAN 27-5 Well # 86 Location: Unit 14 Sec 9 Twn 27 Rge 5

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 0
Int. Casing Pres. N/A

Pressured annulus up to _____ psi. for 30 mins. Test passed/failed

REMARKS: 1000 PSI SPALLING, 60 MINUTE CLOG
THE CASING WAS PRESSURED UP TO 570 PSI AND PRESSURE
CLIMBED TO 580 AND PRESSURE HELD FOR THE LAST 25 MINUTES

By Don Shurt
(Operator Representative)

Witness John D. Han
(NMOCD)

Site Supervisor
(Position)

NMOCD

Revised 02-11-02

MAY 31 2019