

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

5. Lease Serial No.

NMSF078945

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

7. If Unit of CA/Agreement, Name and/or No.

San Juan 29-7 Unit

8. Well Name and No.

SAN JUAN 29-7 UNIT 586S

2. Name of Operator

Hilcorp Energy Company

9. API Well No.

3003929880

3a. Address

382 Road 3100, Aztec, NM 87410

3b. Phone No. (include area code)

505-599-3400

10. Field and Pool or Exploratory Area

BASIN FC/BLANCO PC

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit J (NWSE), 1715' FSL & 1725' FEL, Sec. 27, T029N, R007W

11. Country or Parish, State

RIO ARRIBA, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Interim Reclamation
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company conducted a legacy interim reclamation inspection on 5/14/2019 with BLM Inspector Bob Switzer and received approval for the reclamation BMPs on the subject well.

NMOC

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Kandis Roland

Title **Operations/Regulatory Technician - Sr.**

Signature

Kandis Roland

Date **5/14/2019**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Accepted for Record

Title

Office

Date

MAY 22 2019

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC

RCC Reclamation Completion				Location Name: SAN JUAN 29-7 UNIT 586S		Date: Revision 3 (3/21/17)								
API#: 3003929880				UL-Sec-Twn-Rng: J 27 029N 007W		Lat/Long: 36.69427, -107.55456 NAD 27								
Surface Owner:				Lease#: SF-078945		County/State: RIO ARRIBA, NM								
Pipeline Owner: ENT				Twin/Co-locate Well Name & Operator:										
Onsite: Dale Crawford		Agency Inspector: Bob [Signature]		Contractor:		Seed Mix:								
Interim Reclamation		Completed	Incomplete	N/A	Final Reclamation		Completed	Incomplete	N/A	Remediation		Completed	Incomplete	N/A
Have pit sample results been approved					3rd party pipeline removed					Facilities stripped				
Has water been removed from pit					Anchors removed					Certificate of waste issued & approved				
Have pit marker photos been taken					Equipment and piping removed					Depth:				
Has certificate of waste been issued & approved					Power poles removed					Width:				
Have all pit contents been removed					Cathodic protection removed					Length:				
Has sample after content removal been taken					Vegetative cages removed					Date of Excavation Start:				
Is location contoured					CMP's removed					Date of Excavation End:				
Is there 4' of cover over pit					Non native gravel buried or removed					Date of Backfill Start:				
Has top soil been spread evenly					Noxious weeds removed or sprayed					Date of Backfill End:				
Has all non-native gravel been buried or removed					Invasive weeds removed or sprayed					Yards Hauled Out:				
Has pit liner been removed					Contouring complete					Impacted Soil Hauled To:				
Has all trash been removed					Top soil spread					Yards Hauled In:				
Have all weeds been removed					Diversion clean and functional					Fresh Soil Hauled in From:				
Teardrop allows vehicle access to all facilities					Silt trap clean and functional					Approval to backfill				
Drainage ditches allow adequate run off					Cattle guard / gates removed					Back fill mechanically compacted				
All non-traffic areas disked properly					Cellar / mouse hole covered					Facilities reset				
All non-traffic areas seeded					Erosion under control					Trash and debris removed				
Seeded areas have been mulched					Location properly ripped					Close Out Completed				
Noxious weeds have been removed or sprayed					Location properly disked					Soil Removal Sundry Ready to be Filed				
Invasive weeds have been removed or sprayed					Location seeded									
Barriers set to deter traffic					Photo transect installed									
Silt traps are functional					Access road properly closed									
Culverts are functional					Public use controlled									
Upper diversion is functional					Barriers in place									
Erosion under control					Grazing controlled									
Photo transect installed					P&A marker installed & legible									
Have wellhead cages and jersey barriers been removed					Well sign removed									
Have reclamation pictures been taken					Growth at least 70%									
Growth at least 70%					Trash and debris removed from location									
Agency Inspection Date: 5/14/19					Final reclamation photos taken									
Sundry is ready to file					Agency Inspection Date:									
					FAN Ready to be filed									
Comments:				Comments:				Comments:						