Submit 1 Copy To Appropriate District State of New Mexico	Form C-103	
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 States in Strets St. Artesia NM 88210 OIL CONSERVATION DIVISION	30-031-20133	
<u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410         Santa Fe, NM 87505           District IV - (505) 476-3460         Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Santa Fe Railroad A	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 80	
2. Name of Operator Dominion Production Company, LLC	9. OGRID Number	
3. Address of Operator	10. Pool name or Wildcat	
1414 W Swann Av, Suite 100, Tampa, FL 33606	Lower Hospah	
4. Well Location Unit Letter P : 630 feet from the S line and	<u>1310</u> feet from the <u>E</u> line	
Section 1 Township 17N Range 9W	NMPM County McKinley	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6993' GR		
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	ILLING OPNS. P AND A 🛛	
	_	
OTHER: OTHER: OTHER:	d give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co		
completion or recompletion.		
Dominion completed the plugging of this well as per the attached . We will s	ubmit final after surface reclamation is complete	
Dominion completed the plugging of this wen as per the attached . We will s		
ESTIMATED START DATE 5/15/19		
Approved for plugging of wellbore only.	NMOCD	
Liability under bond is retained pending	MAY O & COLO	
Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web	MAY 3 n 2019	
page under forms	DISTRICT III	
PNR MILLA		
Spud Date: 5/15/19 Rig Release Date:		
Spud Date: 5/15/19 Rig Release Date:	5/17/19	
I hereby certify that the information above is true and complete to the best of my knowledge	ge and belief.	
X M		
SIGNATURE TITLE President		
	DATE 5/29/19	
Type or print name David Burns E-mail address: burnsdavid@ve	DATE	

5

APPROVED BY:	TITLE UPERVISOR DISTRICT #3DATE 6/17/19
--------------	---

## **Dominion Production**

### Plug And Abandonment End Of Well Report

### Santa Fe Railroad A #80

630' FSL & 1310' FEL, Section 1, T17N, R9W

McKinley County, NM / API 30-031-20133

### Work Summary:

- **5/15/19** Made NMOCD P&A operations notifications at 1:00 PM MST.
- **5/16/19** MOL and R/U P&A rig. Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. L/D 64 rods and pump. N/D wellhead, N/U BOP and function tested. TOOH and L/D 2-3/8" production string. P/U 52 joints of 2-3/8" work string to 1647'. R/U cementing services. Circulated the wellbore clean with 50 bbls of fresh water. Pumped plug #1 from 1647'-1430' to cover the Upper Hospah perforations and formation top. WOC overnight. Shut-in well for the day. Jonathan Kelly was NMOCD inspector on location.
- 5/17/19 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. TIH and tagged plug #1 top at 1488'. R/U wire line services. Ran CBL from top of plug #1 at 1488' to surface. CBL results were sent to NMOCD offices for review. R/U cementing services. Attempted to pressure test casing to 800 psi in which it failed to hold pressure. Pumped plug #2 from 750'-120' to cover the Mancos formation top. R/U wire line services. RIH and perforated squeeze holes at 100'. R/U cementing services. Successfully established circulation down through perforations at 100' and back around and out Bradenhead valve at surface. Successfully circulated cement down through perforations at 100' and back around and out Bradenhead valve at surface. N/D BOP and cut-off wellhead. Ran weighted tally tape down both surface and production casings and tagged cement 65' down in both casings. Ran 34" poly pipe down both casings and topped-off well with 50 sx of cement. Installed P&A marker per NMOCD/BLM standards. Photographed the P&A marker

in place and recorded its location via GPS coordinates. R/D and MOL. Jonathan Kelly was NMOCD inspector on location.

### **Plug Summary:**

# Plug #1: (Upper Hospah Sand Perforations and Formation Top 1647'-1488', 25 Sacks Class G Cement)

Mixed 25 sx Class G cement and spotted a balanced plug to cover the Upper Hospah Sand perforations and formation top.

### Plug #2: (Mancos Formation Top and Surface Casing Shoe 750'-Surface, 165 Sacks Class G Cement(50 sx for top-off))

Pumped plug #2 from 750'-120' to cover the Mancos formation top. R/U wire line services. RIH and perforated squeeze holes at 100'. R/U cementing services. Successfully established circulation down through perforations at 100' and back around and out Bradenhead valve at surface. Successfully circulated cement down through perforations at 100' and back around and out Bradenhead valve at surface. N/D BOP and cut-off wellhead. Ran weighted tally tape down both surface and production casings and tagged cement 65' down in both casings. Ran ¾" poly pipe down both casings and topped-off well with 50 sx of cement. Installed P&A marker per NMOCD/BLM standards. Photographed the P&A marker in place and recorded its location via GPS coordinates. R/D and MOL.

## Wellbore Diagram

Santa Fe Railroad A #80 API #: 3003120133 McKinley County, New Mexico

Surface Casing

8.625" 24# @ 62.5 ft

### Plug 2

750 feet - Surface 750 feet plug 165 sacks of Class G Cement 50 sacks for top-off

#### Plug 1

1647 feet - 1488 159 feet plug 25 sacks of Class G Cement <u>Formation</u> Mancos - 530 ft Gallup - 1563 ft



Retainer @ 1647 feet

Production Casing 5.5" 14# @ 1600 ft

