Submit One Copy To Appropriate District Office	State of New Me		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.
District II	OIL CONSERVATION DIVISION		30-045-22483
811 S. First St., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	r., Santa Fe, NM		LG-1917
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Mesa
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 2
2. Name of Operator	MOCD		9. OGRID Number
Dugan Production Corp.		010	006515
3. Address of Operator PO Box 420, Farmington, NM 8749	499-0420		10. Pool name or Wildcat Ballard Pictured Cliffs
4. Well Location DISTRICT III		Danald Fletared Cinits	
Unit Letter <u>C</u> : <u>990</u> feet from the <u>North</u> line and <u>1600</u> feet from the <u>West</u> line			
Section <u>16</u> Township <u>24N</u> Range <u>8W</u> NMPM <u>San Juan</u> County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
6901'GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR			
		CASING/CEMEN	
OTHER: Image: Construction is ready for OCD inspection after P&A Image: Construction of the Construction o			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 			
retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE			
TYPE OR PRINT NAME Kevin Smaka E-MAIL: kevin.smaka@duganproduction.com PHONE: 505-325-1821			
ro, state ose only	D PAI		
APPROVED BY:	- DENI	ED .	DATE
Conditions of Approval (if any):	1 antion is ant carly C	colonge Nipe style	at Card h. Markanad

hocation is not ready for release, pipe sticking out of grand by Marker and BY: Jonathan Kelly several pieces of liner across location. DATE: <u>5/22/2017</u> (505) 334-6178 Ext. 122