| This form is not to be |
|-------------------------|
| used for reporting |
| packer leakage tests |
| in Southeast New Mexico |

Oil Conservation Division

Northwest New Mexico Packer-Leakage Test

Page 1 Revised June 10, 2003

| Operator Hilcorp | Energy Comp | any | | Lea | ise Name | APACHE | | | | Well No. | 1 |
|-------------------|-------------|-----|-----|-----|----------|--------|-----|------|-------|-------------|---|
| Location of Well: | Unit Letter | D | Sec | 18 | Twp | 026N | Rge | 003W | API # | 30-039-2019 | 9 |

| | Name of Reservoir or Pool | Type of Prod | Method of Prod | Prod Medium |
|---------------------|---------------------------|-----------------|-------------------|----------------|
| Upper Completion | GL | Gas | Flow | Tubing |
| Lower Completion | DK | Gas | Flow | Tubing |

Pre-Flow Shut-In Pressure Data

| Completion | Hour, Date, Shut-In 6/11/2019 | Length of Time Shut-In | SI Press. PSIG 259 | Stabilized?(Yes or No) Yes |
|------------|----------------------------------|------------------------|-----------------------|-------------------------------|
| | Hour, Date, Shut-In 6/11/2019 | 185 | SI Press. PSIG 523 | Stabilized?(Yes or No) Yes |

| | | FIO | w Test No. 1 | | |
|---------------------|-------------|------------|--------------|----------------------|--------------|
| Commenced at: | 6/18/2019 | | Zone Pro | oducing (Upper or Lo | ower): LOWER |
| Time (date/time) | Lapsed Time | PRESSURE | | Prod Zone | |
| | Since* | Upper zone | Lower zone | Temperature | Remarks |
| 6/18/2019 5:35 PM | 17 | 259 | 156 | | |

....

.

Production rate during test

| Oil: | BPOD Based on: | Bbls. In | Hrs. | Grav. | GOR | |
|------|----------------|----------|------|-------|-----|--|
| | | | | | | |

Gas MCFPD; Test thru (Orifice or Meter)

Mid-Test Shut-In Pressure Data

| Upper Completion | Hour, Date, Shut-In | Length of Time Shut-In | SI Press. PSIG | Stabilized?(Yes or No) | |
|---------------------|---------------------|------------------------|----------------|------------------------|--|
| Lower Completion | Hour, Date, Shut-In | | SI Press. PSIG | Stabilized?(Yes or No) | |

(Continue on reverse side)

NMOCD JUN 2 5 2019 District III

Northwest New Mexico Packer-Leakage Test

, ••

Flow Test No. 2

Page 2