



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/oed/District III/3distric.htm](http://emnrd.state.nm.us/oed/District%20III/3distric.htm)

НМООД

MAY 03 2019

DISTRICT III

(submit 1 copy to above address)

Date of Test 5-3-19 Operator Hilcorp E. Co. API #30-0 3930571
Property Name SS-28-5kt Well No. 74N Location: Unit G Section 36 Township 28 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 118 Intermediate 0 Casing 122 Bradenhead 0

PRESSURE

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	122	0	125
10 min	0	0	123	0	125
15 min	0	0	124	0	125
20 min				0	126
25 min				0	126
30 min				0	126

Steady Flow	<i>vapors</i>
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

REMARKS: Btl. Nothing When Opened - Nothing When
Opened after 15 min Shut in - Int. Blow thru 4" for 1 min & 5 seconds then thru 2" to head at 2 min. Vapors
By FZS
Witness Monica Lucking with Black
Spotting water
and Sludge.
5-10-15 Vapors-

By [Signature]
(Position)

E-mail address _____

Blow when opened 20-25-30
after 5 min shut in