



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 14-JUNE-2014 Operator HILCOLP API #30-045-27456

Property Name KAH DESPAH Well No. 2 Location: Unit K Section 18 Township 24 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 570 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	N/A	560		
10 min	0		550		
15 min	0		550		
20 min	0		550		
25 min	0		540		
30 min	0		540		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By [Signature]  
Wellsite Supervisor  
(Position)

Witness [Signature]

E-mail address \_\_\_\_\_

NMOC  
JUN 17 2014  
DISTRICT III