



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

DEC 1 2017

MAY 31 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-30-19 Operator Hilcorp Energy Co API #30-0 39-07822

Property Name SS30514 Well No. 33 Location: Unit 20 Section 20 Township 30 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 301 Intermediate 128 Casing 128 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	307	130	141	130
10 min	0	307	135	60	130
15 min	0	307	135	21	130
20 min				5	130
25 min				0	130
30 min				0	130

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	☐
Down to Nothing	☒
Nothing	☐
Gas	☒
Gas & Water	☐
Water	☐

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH light blow to dead at 12 seconds nothing when opened after 5 min shut-in - Int - hard blow when opened - Out 25 but still blowing - dying slowly.

By AC Grey C

Witness Monica Kuehling

(Position)

E-mail address _____

Gas analysis
Out 5 min shut-in with med.
blow.